

CWB7 Weighing Indicator



PCS



CHECK



BAT INT

Tare, Units, Net/Gross, Print, Zero, On, Off
Weighing, Counting Function, Check weight HI-OK-LO
Multiple Weighing Units
Power On Zero-Tracking
Auto-Power Off mode,
Digital Noise Filter,
Full range tare,
Accumulation Memory,
Low Battery Indicator
Charging Status Indicator
Bench or pole mount
Display: 6 digits LCD 40mm with white backlight
Rechargeable battery 6V/4Ah 80 hours continuous use
Power Supply: Input AC 100V-240V, Output 12V/1A C+
Operating temperature: -10°C to 40°C
Product size: 240 mm x105 mm x 180 mm
up to 4 load cell 350ohm minimum resistance
Display Resolution:30,000 divisions
Internal Resolution 600,000 divisions

