

BR-10 General purpose weighing scale



Features:

- ABS housing
- Backlight LCD with six 25mm high digits
- Backlight display selectable: automatic, always on and deactivated.

- Operating temperature range: -10°C +40°C.

- Power supply adaptor AC/DC 240Vac 50Hz.
- Lithium battery.
- Programmable gravity
- Weighing units: g/kg/lb./lb.-oz.
- Single range or multi-range.
- Auto switch off (programmable: from 1 to 99 minutes)

Functions:

- Accumulation
- Totalization
- Piece counting
- Zero
- Stability modes: deactivate, animal weighing, peak value hold.
- Stable weight and stable weight with auto cancel at zero
- Check weight (limits function) with visual signal and alarm.
- Tare

BR-10 General purpose weighing scale

Colour display checkweighing function for high/low/OK target weight.

